

KU-KEN-1028

No.TCD- 1817-79

Date December 18,1979

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: Mitsubishi models MU-2B, MU-2B-10/-15/-20: S/N 005 thru 164
(except aircraft that has previously complied with Mitsubishi MU-2 Service Recommendation No.033 or 033A)

2. Compliance required as indicated •

To prevent the possible fire in the baggage compartment due to the contact of baggage with the engine bleed air lines, unless already accomplished, within the next 200 hours time in service after the effective date of this AD, accomplish the modification of the baggage compartment ceiling in accordance with "Instructions" of Mitsubishi MU-2 Service Bulletin No.182 dated Nov 16,1979 or its later JCAB approved revisions.

3. Remarks

3.1 Effective date: January 31, 1980

3.2 Mitsubishi MU-2 Service Bulletin No.182 dated Nov 16, 1979 or later JCAB approved revisions pertain to this subject.