

KU-KEN-447

No. TCD-630-69

Date Dec. 23, 1969

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to:

NAMC YS-11 series airplanes having Dowty Rotol Accessory Gearboxes, the type numbers of which are specified in each paragraph 1.A Part 1 and Part 2 of D.R. Service Bulletin No. 83-297 Rev. 6 or later revisions, No. 83-331 Rev. 5 or later revisions, or No. 83-338 Rev. 1 or later revisions, except those having accomplished the modifications in accordance with D.R. Service Bulletin No. 83-384 Rev. 3 or later revisions.

2. Compliance required as indicated

To prevent possible fatigue failure occurring in the tunnel drive shaft and excessive wear on the tunnel shaft serrations, accomplish the modifications at next overhaul of Gearboxes, unless already accomplished, in accordance with D.R. Service Bulletin No. 83-297 Rev. 6 or later revisions, No. 83-331 Rev. 5 or later revisions, or No. 83-338 Rev. 1 or later revisions.

Japan Civil Aviation Bureau

No. TCD

Sheet 2

3. Remarks:

3.1 Effective Date: December 23, 1969

3.2 Dowty Rotol Service Bulletin No. 83-297 Rev. 6 (dated June, 1969), No. 83-331 Rev. 5 (dated June, 1969) and No. 83-338 Rev. 1 (dated June, 1969) covers this subject.