# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~/Import Vehicles

| | | | |
|---|---|---|---|
| CAMPAIGN No. | Gai-1772 | DATE | 4/Aug/2011 |
| MANUFACTURER | VOLVO CARS CORPORATION | | |
| DESCRIPTION OF DEFECT | Volvo Car Corporation (VCC) has decided to carry out a safety recall on a limited number of Volvo S80 vehicles (model year 2007), equipped with 6 cylinder engine.<br>VCC has found that the power steering return line may burst due to incorrect routing of the power steering line. Should this condition occur, it may result in a sudden drainage of power steering oil and a loss of power steering assistance and in worst case scenario a fire in the engine compartment. Since this may appear suddenly and without any relevant warnings to the driver, this condition poses an unreasonable risk to motor vehicle safety.<br>The corrective action will be to inspect if the power steering cooling line is correctly routed. Concerned parts will be replaced if necessary. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---|---|---|---|
| VOLVO | S80 | 2007 | 597 |
| | | TOTAL | 597 |