VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4550	DATE	August 21,2019
MANUFACTURER	TOHO CAR CORPORATION		
DESCRIPTION OF DEFECT	There is a small clearance between the air hose fitting connected to the brake chamber, which is a component of the trailer braking system, and the air tank, and there is a risk that they will come in contact with each other when the step is run up. In the event of contact, the air hose connection port of the brake chamber may be damaged, the main braking capability may be insufficient, or the parking braking device may be activated, which may cause a problem in traveling.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TC28H8B2	Semi-trailer	2017	49
		TOTAL	49