VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~／Import Vehicles

| | | | |
|---|---|---|---|
| CAMPAIGN No. | GAI 4191 | DATE | Sep, 10, 2026 |
| MANUFACTURE | SCANIA CV AB<br>（Japanese Importer: SCANIA JAPANA Co. Ltd.） | | |
| DESCRIPTION OF DEFECT | In the gearbox of the power transmission system, the design of the pin that secures the gear shift fork to the gear selector shaft is inadequate. Repeated gear-shift operations under high load conditions may cause the pin to loosen. This can result in gear-shifting malfunctions, such as extended shift times or failure of the selected gear to engage properly. If the vehicle continues to be operated in this condition, gear changes may not be carried out as intended, which could lead to a mismatch between the actual gear engaged in the transmission and the gear position indicated in the instrument cluster. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---|---|---|---|
| SCANIA | LPGRS series Truck | 2024 - 2026 | 783 |
| | | TOTAL | 783 |