VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	５４３２	DATE	January 23,2024
MANUFACTURER	NICHIJO CORPORATION		
DESCRIPTION OF DEFECT	In the frame of a rotary snowplow,Cracks may occur in the vehicle frame due to insufficient strength of the vehicle frame. Therefore, if you continue to use it as it is, the cracks will progress and in the worst case,There is a risk that the vehicle frame may break.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-R01E	HTR608	2015～2023 R01E-0001～R01E-0023	14
		TOTAL	14

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.