VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5876	DATE	September. 3. 2026
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Due to improper factory repair work, the lock nut tightening torque of the parking lock plate at some play adjustment sections in the packing lock lever are insufficient. Therefore, the nuts loosen due to vibration during driving, and when the play exceeds the specified value, the parking brake does not operate even if the parking lock lever is operated, which could cause parked vehicles to start moving. In addition, the swing lock mechanism* may not operate, causing the vehicle to tilt and roll over while parked. *Retains the upright position of the vehicle when the parking brake is activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAD-EF14	「GYRO CANOPY e:」	2023～2024	109
		TOTAL	109