英文リコール概要書

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5869	DATE	9/4/2026
MANUFACTURER	HANAMIDAI Auto Co., Ltd.		
DESCRIPTION OF DEFECT	Due to improper work management, some cargo bed spacer fixing bolts were installed in the reverse direction of the normal orientation. Therefore, tire oscillation during driving may cause contact between the bolt tip and the tire. In the worst-case scenario, the tire could be damaged, and its debris could fall off and obstruct other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-NKR88AM	「ELF」	NKR88-7027923 ～ NKR88-037693 10/18/2023 ～ 9/10/2024	107
2RG-AKR88AM	「ATLAS」	AKR88-7000290 ～ AKR88-7000323 6/7/2024 ～ 9/11/2024	3
		TOTAL	110