VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	２９６５	DATE	Jul.11, 2012
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	With regard to the joint between an inner leg assembly and a part which is connected to the shaft that raises and lowers the auxiliary legs, some of those inner leg assemblies are not fixed enough because in the course of crimping, performance of the processing jigs was not efficient. Thus, the joints might become unsteady, and in the worst case, the inner leg assemblies could incline, and it shall be impossible to raise or lower the auxiliary legs, unless further use should be avoided.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DFWTF241B	Van Semi Trailer	2012	20
KFKHH340	Semi Trailer	2012	10
KFKGG340W	Semi Trailer	2012	5
		Total	35