VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No..	4780	DATE	JULY-28-2020
MANUFACTURER	Topre Corporation		
DESCRIPTION OF DEFECT	At van-type truck with a gross vehicle weight of 3.5 tons or less, the auxilialy break light mounting position dose not meet the Car safety standards 39-2 (standard of auxiliary brake lights) because the auxiliary break light is not instilled proper position.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDF-KDY271	DYNA	2018	1
QDF-KDY221		2015	1
CBF-SQ2F24	ATLAS	2018～2020	15
EBD-DR16T	CLIPPER	2018	5
		TOTAL	22