VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAL-3231	DATE	2021/06/08
MANUFACTURER	Tesla, Inc. (Japanese Importer; Tesla Motors Japan)		
DESCRIPTION OF DEFECT	The brake calipers of Model 3 vehicles are attached to the wheel knuckle using two fasteners that are torqued to correct specifications. If a fastener is not secured at the specified torque and angle, the fastener may loosen over time and, in the very rare circumstances, may become loose enough such that the caliper makes contact with the inner surface of the wheel rim.		

Type	Commercial name	MODEL YEAR RECALLED	Number of Vehicle
ZAA-3L13	Model 3 RWD	2019-2020	18
ZAA-3L23	Model 3 AWD	2019	2
ZAA-3L23P	Model 3 AWD	2019-2020	8
Total	3 kinds	2019-2020	28