VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No..	5039	DATE	15-10-2021
MANUFACTURER	Topre Corporation		
DESCRIPTION OF DEFECT	In the remote control Box fixing bracket of the air suspension of refrigerated / frozen trucks.As shown in the figure, the bracket is not welded in the proper position and the bracket is cracked may occur. Therefore, if the bracket is used as it is, cracks will develop, and in the worst case, it will break.The air suspension remote control Box may fall off and interfere with other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FC2ABG	HINO RANGER	2017～2020	30
2KG-FD2ABG		2017～2018	13
2PG-FC2ABG		2017～2018	2
2PG-FD2ABG		2017	2
2PG-FE2ABG		2017～2018	3
		TOTAL	50