第4号様式（英文リコール概要書）（第2関係）

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicies

CAMPAIGN No.	外－3543	DATE	2023/1/11
MANUFACTURER	MASSEY FERGUSON (Japanese Importer :MSK Farm Machinery Corporation CEO Saito Yoshiyuki)		
DESCRIPTION OF DEFECT	In the gearbox of agricultural tractor, the bearing for 1st gear may disengage because of insufficient tightening of their retaining bolts. Therefore if the vehicle is used as it is, the 1st gear may fail and the tractor may become unable to move. We will replace and tighten the retaining bolts to the specified torque. In case of bearing or gear failure, we will replace them with new parts.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-SU44AC	MF5710-4C	2019	12
YDR-SU44AC	MF6713-4C	2019	7
	MF6713-4F	2019	1
		TOTAL	20

（日本工業規格A列4番）