

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI 4231	DATE	Aug. 27, 2026
MANUFACTURE	SCANIA CV AB (Japanese Importer: SCANIA JAPANA Co. Ltd.)		
DESCRIPTION OF DEFECT	Due to insufficient design consideration of the operating voltage tolerance range of the power supply circuit for the microcontroller in the climate control unit, the operating voltage may fall outside the normal operating range of the microcontroller under certain conditions. As a result, the climate control unit may shut down, causing the air-conditioning blower fan to stop operating. Consequently, the defroster may become inoperative, resulting in a potential non-compliance with regulatory requirements.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2024	32
		TOTAL	32