

TIRE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Tires

CAMPAIGN No.	Sou-2 1	DATE	Aug. 27 th , 2026
MANUFACTURER	THE YOKOHAMA RUBBER CO., LTD.		
DESCRIPTION OF DEFECT	Tire (Possible air leakage from a tire bulge) Due to miss-handling on production control, some of the tires manufactured at the Mie Plant may not have proper adhesion at sidewall components as designed. This may cause sidewall bulge, which in the worst case air leakage disabling the tire. The tires of the subject production number tires will be replaced with good ones.		

COMMERCIAL NAME	TYPE	CLASSIF ICATION	MODEL YEAR RECALLED	NUMBER OF TIRES
LT151R	205/85R16 117/115N	For Light Truck	FB MO YY 2226 31 st May. 2026 ~ 6 th Jun. 2026	6 pcs

Total	6 pcs
-------	-------

*Among the serial number, subject production numbers are listed in the appendix table.

205/85R16 117/115N LT151R

6 pcs

Table. Tire serial and production number

Tire serial	Production number
FBMO YYY2226	E540061KDW
FBMO YYY2226	E540061KDZ
FBMO YYY2226	E540061KE1
FBMO YYY2226	E540061KE3
FBMO YYY2226	E540061KE6
FBMO YYY2226	E540061KE8