

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-4224	DATE	26.08.2026
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	During repeated engine starts and in start-stop operation, the contacts experience abnormal wear, and wear particles may accumulate beneath the lower contact point. Over the service life of the starter, this impairs the engine's starting capability. Under certain circumstances, it may no longer be possible to start the engine. In the worst-case scenario, there is a risk of fire either when activating the starter or while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-12CM20	「BMW 220i」	2023-2025	716
3BA-5F20	「BMW 318i」	2022-2025	1,893
	「BMW 320i」	2022-2025	1,710
3BA-6K20	「BMW 318i Touring」	2022-2025	1,137
	「BMW 320i Touring」	2022-2025	890
3DA-5V20	「BMW 320d xDrive」	2022-2025	3,183
3DA-6L20	「BMW 320d xDrive Touring」	2021-2025	2,576
3BA-12AP20	「BMW 420i Coupe」	2022-2025	793
	「BMW 420i Cabriolet」	2022-2025	550
3BA-12AV20	「BMW 420i Gran Coupe」	2022-2025	1,409
3DA-32AX20	「BMW 420d xDrive Gran Coupe」	2022-2025	1,946
3BA-JR20S	「BMW 523i」	2020-2023	219
	「BMW 530i」	2020-2023	161

3DA-JF20	「BMW 523d xDrive」	2022-2023	237
3DA-JP20	「BMW 523d xDrive Touring」	2022-2024	134
3BA-JT20T	「BMW 530i Touring」	2020-2024	251
3BA-TY20	「BMW X3 xDrive20i」	2022	18
3DA-UZ20	「BMW X3 xDrive20d」	2020-2024	4,134
3DA-VJ20	「BMW X4 xDrive20d」	2023-2024	1,596
3BA-HF20	「BMW Z4 sDrive 20i」	2022-2025	636
		TOTAL	24,189