

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	GAI-4215	DATE	2026/8/20
MANUFACTURER	Massey Ferguson (Japanese Importer :MSK Farm Machinery Corporation CEO Kota Kambara)		
DESCRIPTION OF DEFECT	Due to improper molding conditions during manufacturing, blowholes (voids) may form around the retaining nuts inside the plastic fuel tanks of agricultural tractors, resulting in insufficient resin filling. With continued use, cracks may develop from these areas, which could lead to fuel leakage from the tank in the worst-case scenario. For all affected vehicles, the fuel tank will be replaced with an improved part.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-SU33AF200	F211VARIO G3	2025	2
		TOTAL	2