

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-4229	Date	August 18, 2026
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	The Front-End Auxiliary Drive (FEAD) belt idler pulley may over-rotate following a high-torsion input, and lead to a clash with and damage to the oil pressure sensor. Replace the idler pulley.		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-L123WA	Range Rover Sport	2024	321
3CA-LE62WAB	DEFENDER	2024 -2026	533
3CA-LE62WCB			121
3CA-LE72WAB			5,802
3CA-LE72WCB			761
3CA-LK93WA	Range Rover	2024	38
3CA-LR3WB	Discovery	2024 - 2026	222
7CF-LE73WVE	Hard Top X-Dynamic	2026	1
		Total	7,799

(JIS A4 size)