VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/(Import Vehicles)

CAMPAIGN No.	Gai-4234	DATE	17.09.2026
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In the vehicles concerned, water can penetrate at certain points on the starter motor and cause damage. It may then no longer be possible to start the engine. This may also result in a short circuit or the starter motor becoming permanently activated. This may result in localized overheating of the starter motor or thermal overload of surrounding components. At worst, this may result in a vehicle fire. This can also occur when the vehicle is parked.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-8E20	「BMW 330e」	2015- 2018	1,781
3LA-JA20PH	「BMW 530e iPerformance」	2019-2020	9
CLA-JA20P	「BMW 530e iPerformance」	2017-2020	1,685
DLA-7D20	「BMW 740e iPerfomance」	2016-2018	1,332
		TOTAL	4,807