VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4239	DATE	September 16, 2026
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	Due to insufficient design consideration of the valve in the fuel breather system that regulates the internal pressure of the fuel tank in four-wheel-drive vehicles, some valves may not close properly. Consequently, when the fuel tank internal pressure rises, fuel may enter the ACF (charcoal canister), which may result in a fuel leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-FVDNFF	Audi TTS	2023	86
3BA-FVDNPF	Audi TT 45Tq	2023	164
3BA-GADNFF	Audi SQ2	2023	12
3BA-GYDNFF	Audi S3	2023	105
3BA-GYDNNF	Audi A3 40Tq	2023	343
3BA-GYDNWF	Audi RS3	2023	148
		Total	858