VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-4235	DATE	15. 09. 2026
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to a manufacturing defect, the clutch cable's engine-side nipple may loosen. As a result, the clutch can no longer be operated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-F902A	「BMW F800GS」	2025 - 2026	26
8BL-F902A	「BMW F900R」	2025 - 2026	15
8BL-F902A	「BMW F900XR」	2025 - 2026	60
		TOTAL	101