Form No. 4: Summary of Recall in English (Related to Article 2)

Vehicle Safety/Pollution Recall in Japan

Import Vehicles

Campaign No.	Gai-4233	Date	Sep. 8, 2026
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	Water management system on the tailgate of the vehicle may not be sufficient to allow water to drain away from the rear view camera. This can allow water to pool around the camera installation and, over time, can cause damage to the camera. Modify the water drain hole.		

Type	Commercial name	Model year recalled	Number of vehicles
3AA-LR3UB	Discovery	2021 - 2023	21
3CA-LR3WB		2021 - 2025	374
7AA-LR3UC		2024	2
		Total	397