

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5865	DATE	August 20,2026
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inadequate control programs in the navigation system, it may not be possible to boot, reboots may occur during use, the liquid crystal display may turn black or freeze, or unintended screen scrolling may occur. Therefore, if the liquid crystal display does not display the camera image when checking the front and left side area of the vehicle or while reversing, the vehicle may not conform to safety regulations.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5LA-GN0W	「OUTLANDER PHEV」	2024～2026	13,226
		TOTAL	13,226