

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5867	DATE	Aug. 20 2026
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some manually foldable left-side mirrors, due to an insufficient consideration of the evaluation method, cracks may occur in the unit flange of the manually foldable unit, such as those caused by vibrations during driving. If the vehicle continues to be used in this condition, the cracks will progress, and the mirror may fall off in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-MM96FH	「FUSO AERO ACE」	2011 ~ 2011	2
TDG-MM97FH		2014 ~ 2017	5
QDG-MM97FH		2017	1
QTG-MS96VP		2017 ~ 2017	31
QTG-MS96VP	「FUSO AERO QUEEN」	2017	1
		TOTAL	40