VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5866	DATE	September 4, 2026
MANUFACTURER	SHINMAYWA INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	On dump trucks with a sliding body, due to inappropriate assembly process of the stay for dumper hydraulic oil tank, space between the said stay and brake pipe for rear wheels is small, thus these components may contact each other under vibration while driving. Therefore, if the operation in aforementioned state would continue, the brake pipe may be damaged, and in the worst case brake fluid may leak causing decreased brake force.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-NPR88YM	ISUZU ELF	2024～2026	247
2RG-NPR88YM		2024～2026	212
2WG-NPR88YM		2026	2
		TOTAL	461