VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Domestic／~~Import~~ Vehicles

| | | | |
|---|---|---|---|
| CAMPAIGN No. | 5871 | DATE | September 9, 2026 |
| MANUFACTURE | SUMITOMO NACCO FORKLIFT CO., LTD.<br>(Japan) | | |
| DESCRIPTION OF DEFECT | For special-configuration vehicles, due to insufficient design review, the rear-view mirror is installed in a position that does not satisfy the visibility test requirements. As a result, rear traffic conditions cannot be adequately observed, causing non-compliance with the applicable safety standards. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---|---|---|---|
| EBT-SG2J-1 | FG20PAXIII | 2021 - 2025 | 3 |
| EDM-SD2E | FD20PAXI<br>FD25PAXI | 2009 - 2015 | 7 |
| YDN-D3K | FD30PAXIII<br>FD35PAXIII | 2024 - 2025 | 6 |
| YDN-SD2G | FD25PAXIII | 2020 - 2026 | 9 |
| EBT-SG1KT-1 | FT15PAXIII | 2023 - 2024 | 2 |
| EDM-D3J | FD30PAXI | 2015 | 1 |
| KDN-D2L | FD25PAXI | 2009 | 1 |
| | | TOTAL | 29 |