VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5874	DATE	September 10, 2026
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	On certain interior materials used for the seat covers and front door armrests, due to insufficient consideration of the surface finishing process, some parts may allow flame propagation at a rate faster than that specified in the flammability test standard. Therefore, the vehicle may not comply with the applicable safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-LA850S	MOVE	2025	8,078
5BA-LA860S			1,425
5BA-LA850F	STELLA		398
5BA-LA860F			190
		TOTAL	10,091