VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) / Import Vehicles

CAMPAIGN No.	5883	DATE	September. 29. 2026
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In the transmission of vehicles equipped with Y-AMT (YAMAHA AUTOMATED MANUAL TRANSMISSION), the shift shaft may break due to repeated shifting because the strength of the shift shafts was not adequately evaluated. As a result, shifting problems may occur and the engine warning light may illuminate, and in the worst case, Y-AMT may stop functioning and it may become impossible to shift gears, making the vehicle unable to be ridden.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-RNA1J	TRACER9 GT+ Y-AMT	2025～2026	686
8BL-RN88J	MT-09 S	2024～2026	603
		TOTAL	1,289