

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2699	DATE	Jan.28.2011
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain medium duty fire cars, due to insufficient cleaning of the parts before installing onto an engine, fine shot peening beads are embedded into the idle gear bush causing the bush to be frozen during the fire equipment operation, resulting in an engine breakdown and inability to restart of it.		

engine

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FD7JEW改	Hino Ranger	2010	2
BDG-FT8JGWL改		2010	1
BDG-GD7JGWA改		2010	3
BDG-GX7JGWA改		2010	32
		TOTAL	38