

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2711	DATE	Feb.17 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	During the manufacturing process of the brake vacuum servo, the diaphragm has been damaged in some of the units. If the servo continues to be used in this condition, the damage may penetrate through the diaphragm. In the worst case, the braking effect will be reduced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-FE71BSD	FUSO CANTER	2010～2010	3
		TOTAL	3