

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2722	DATE	Mar.10.2011
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain medium duty fire cars, due to insufficient cleaning of the parts before installing onto an engine, fine shot peening beads are embedded into the idle gear bush causing the bush to be frozen during the fire equipment operation, resulting in an engine breakdown and inability to restart of it.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-GX7JGWA改	Hino Ranger	2010	1
		TOTAL	1