

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2731	DATE	March.25.2011
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	The precision of gear case cover might not be allowable and cause spline breakage of hydraulic motor drive shaft.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-R430	R430Z	2010 to 2011	142
	6SDTL8	2010 to 2011	39
EDM-R530	R530Z	2010 to 2011	108
	R630Z	2010 to 2011	16
	6SDTL10	2010 to 2011	4
	6SDTL12	2010	1
		TOTAL	310