

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2729	DATE	March 28, 2011.
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	As low beam angle alignment of headlamp for the vehicles with automatic angle adjustment was not made properly, some of the vehicles may not be suited for safety standard of headlamp.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBD-TDA4W	Escudo	2011	39
		TOTAL	39