

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	2733	DATE	Mar.31.2011
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty sight seeing buses equipped with a toilet specified for cold district, due to improper installation work, the electric wire of the heater for the water can be pinched under the tank resulting in a short-circuit of the wiring and smokes at ceiling board if the worst comes.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PKG-RU1ESAA	Hino SELEGA	2009~2010	14
BJG-RU1ASAR		2009	3
		TOTAL	17