VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-1740	DATE	Mar.31.2011
MANUFACTURER	Scania CV AB (publ) (Hino Motors, Ltd.)		
DESCRIPTION OF DEFECT	assembled into their brak the brake pad and the dis	actors, improperly machine e caliper assembly causing k to be adjusted too tight g ng in brake pad drag and sn	the clearance between gradually with vibration

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PK-SHD1EBG	Hino SCANIA	2006~2007	15
PK-SHD1FBG		2006	2
BKG-SHD2EAG		2008~2009	101
BKG-SHD2EAJ			
BKG-SHD2FAG		2008~2009	33
BKG-SHD2FAJ			
		TOTAL	151