VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

	Somestion import veinces				
CAMPAIGN No.	2754	DATE	Мау.31.2011		
MANUFACTURER	YAMAHA MOTOR CO., LTD.				
DESCRIPTION OF DEFECT	As for rearview mirrors, because there is no margin in the dimensions of the jig used in the manufacturing processes, there are some reflectors of the said rearview mirrors of which the dimensions are smaller than they are supposed to be, due to grinding variation after cutting the reflectors. Therefore, there is a possibility that these reflectors may not conform with the safety standards for road trucking vehicles.				

	COMMERCIAL	MODEL YEAR RECALLED		NUMBER OF
TYPE	NAME			VEHICLE
EBL-RN21J	F Z 1	2008~2010		6 8 2
			TOTAL	6 8 2