

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2762	DATE	June 8, 2011
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	On eligible units, the tube might have been pinched between tire and rim due to improper mounting of tube in the front and or rear wheel assembly process. If the pinching is released, the air may leak from the pinched (damaged) area of tube. This results in degraded handling of the motorcycle, creating the possibility of a fall in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBK-BJ250A	ESTRELLA	2011	35
JBK-BJ250F	250TR	2011	23
EBL-EJ800A	W800	2011	826
EBL-VN900B	VULCAN 900 CLASSIC	2011	10
TOTAL			894