

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	2757	DATE	Jun 9,2011
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	IN THE REAR SUSPENSION, SINCE THE STRENGTH OF THE BUSH BRACKET CONNECTING THE REAR LOWER ARM AND THE REAR AXLE HOUSING DOES NOT HAVE ENOUGH MARGIN, IF THE RIGHT AND LEFT TURN OR STOP-START MOVEMENT ARE REPEATEDLY OPERATED, THE BRACKET WOULD GET DAMAGED AND THE CONNECTION BETWEEN THE REAR LOWER ARM AND THE REAR AXLE HOUSING WOULD BE SEPARATED CAUSING A NOISE WHICH COULD RESULT IN THE REDUCTION OF THE DRIVING STABILITY.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GBD-U61V	M I N I C A B	2006 TO 2011	44,993
GBD-U62V		2006 TO 2011	20,669
ABA-U61W	T O W N B O X	2006 TO 2011	2,386
ABA-U62W		2006 TO 2011	4,509
CBA-U61W		2006 TO 2011	4,447
CBA-U62W		2006 TO 2011	978
GBD-U71V	C L I P P E R	2006 TO 2011	45,203
GBD-U72V		2006 TO 2011	15,288
ABA-U71W	C L I P P E R R I O	2007 TO 2011	3,256
ABA-U72W		2007 TO 2011	3,874
CBA-U71W		2007 TO 2011	7,006
CBA-U72W		2010 TO 2011	111
		TOTAL	152,720