

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2768	DATE	June 14, 2011
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Due to poor water resistance of electric valve, water might penetrate to it. Therefore if a machine is continuously used under such condition, short circuit might happen and fuse might be melt down, and a machine can not travel.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-M248	FD60,FD70,FD80	2008~2011	30
		TOTAL	30