

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1761	DATE	Jun. 21 2011
MANUFACTURER	Mercedes-Benz (Japanese importer : Mitsubishi Fuso Truck and Bus Corporation)		
DESCRIPTION OF DEFECT	On some engines for articulated buses, cracks may occur in the high-pressure fuel injection piping due to insufficient strength of the pipes. If the vehicle continues to be used in this condition, fuel may leak from the piping. In the worst case, a fire will occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unclear model	—	2007~2007	4
TOTAL			4