

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic/Import Vehicles)

CAMPAIGN No.	2877	DATE	January 10,2012
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD. 6-1-45, Koshienguchi, Nishinomiya-shi, Hyogo prefecture, Japan		
DESCRIPTION OF DEFECT	<p>Because the management of the caulking tool for the drain cook pin of the air brake tank was inappropriate, the fixation of O ring of that pin became insufficient. On that account, at the operation of drainage, some O rings come off and air leaks from that pin and then parking brake works.</p> <p>In this condition, as the result, the brake equipments will be overheated and lead to a fire in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KTT101	tank semi-trailer	2010~2011	15
KTT241S	tank semi-trailer	2010~2011	12
KL28-37LS1	tank semi-trailer	2011	2
KL28-17LS2	tank semi-trailer	2011	3
KL28-47LS1	tank semi-trailer	2011	2
KL28-17LS3	tank semi-trailer	2011	1
KL16-16AC	tank semi-trailer	2011	1
		TOTAL	36