VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

CAMPAIGN No.	2879	DATE		19,Jan,2012
MANUFACTURER	ShinMaywa Industries,Ltd.			
DESCRIPTION OF DEFECT	Due to installation position of stopper of movable hopper table is inappropriate among GVW 7ton garbage compactor trucks which are equipped with movable hopper table, it is incompatible within safety standard of road trucking vehicle law of visibility of large rear-marking plates.			
TYPE	COMMERCIAL NAME	Y	ODEL ÆAR ÆALLED	NUMBER OF VEHICLE
PKG-FSR90S2	ISUZU FORWARD	2	2011	1
SKG-LK38N		2	2011	1
SKG-MK38L	UD TRUCKS CONDOR	2	2011	2
LKG-PK39LH		2	2011	1
SKG-FC9JDAA	HINO RANGER	2	2011	2
SKG-FC9JEAA		2	2011	2
SKG-FC9JGAA		2	2011	3
SKG-FD9JGAA		2	2011	2
SKG-GC9JJAA		2	2011	1
SKG-GC7JGAA		2	2011	1
SKG-GD7JGAA		2	2011	1
LKG-FE7JEAA		2	2011	1
SKG-FK71F	FUSO FIGHTER	2	2011	2
		ТС	OTAL	20