

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2900	DATE	February 28 ,2012
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the medium-duty truck, the front axle could contact the tie rod due to improper shape of the tie rod when the steering wheel is turned to the maximum limit.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FSR34S2 SKG-FSR34T2	FORWARD	2011	47
SKG-FSR90S2 SKG-FSR90T2		2011	18
		TOTAL	65