

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1825	DATE	April 02, 2012
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	On the fuse box under the bonnet, over tightening of the fixation nut for the electrical supply may occur the diagnostic warning light coming on and engine starting problem.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-A75F01 ABA-A7W5F01	Peugeot 207 Peugeot 207SW	2010-2011	14
		TOTAL	14