

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2924	DATE	April 18,2012
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the sun visor of the passenger side, the caution label for the passenger side airbag has not been attached due to the improper design drawing resulting in the non compliance with the safety standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-U61V	MINICAB	2011 TO 2012	158
EBD-U62V		2011 TO 2012	186
EBD-U71V	CLIPPER	2012	153
EBD-U72V		2012	73
		TOTAL	570