

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-1833	DATE	April 20, 2012
MANUFACTURE	RENAULT SAS (Japanese Importer : Renault Japon Co.,Ltd.)		
DESCRIPTION OF DEFECT	While production of a wire harness for engine room, installation of scratch prevention cover was failed. So the wire harness is possible to be damaged by rubbing during using the vehicle.  After using several term with that situation, the internal electric wire in the wire harness may touch with an engine hanging hook, then they may make an electrical short circuit. In that case, warning light illuminates and engine revolution speed and vehicle speed are limited due to be in safe mode, and exhaust gas may be out of emission standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-DZF4R	Megane	2011	146
		TOTAL	146