

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI – 1838	DATE	April 23 rd 2012
MANUFACTURE	Rolls-Royce Motor Cars Limited The Drive, Westhampnett, Chichester, West Sussex, PO18 0SH, UK (Contact in Japan : Japan Representative Office - R-R Motor Cars Ltd)		
DESCRIPTION OF DEFECT	In some circumstances, a crack may develop in the plastic housing of the auxiliary electric coolant pump for the turbocharger due to an inappropriate manufacturing process. A crack in the housing leads to coolant or moisture penetrate the electronics of the additional coolant pump. It might cause short circuit at the plug connector, which could lead to smoldering of the plug connection and, in worst case, it can cause vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-664S	Rolls-Royce Ghost	2011	3
		TOTAL	3