

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	2930	DATE	April 25,2012
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa ctiy, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	In the rolling pillar in order to fix the wall of the wing track, if the pillar receiving a strong lateral load from the loading platform inside, due to the lack of robustness of the locking device of the pillar, if there is a lock to come off. If this occurred while traveling, the full width of the vehicle does not meet the safety standards for road vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-CYJ77A	GIGA	2010~2011	351
LKG-CYJ77AA	GIGA	2011	4
LKG-CYL77A	GIGA	2010~2011	159
LKG-CYL77AA	GIGA	2011	1
LKG-CYY77A	GIGA	2011	1
LKG-CYY77AY	GIGA	2011	1
LKG-FN1EYBG	PROFIA	2011	1
LKG-FR1EXBG	PROFIA	2011	1
LKG-FW1AXBG	PROFIA	2010~2011	3
LDG-FW1EXBG	PROFIA	2010~2011	19
LKG-FW1EXBG	PROFIA		
LKG-FW1EXBJ	PROFIA		
LKG-FW1EYBJ	PROFIA	2011	1
LKG-FW1EZBG	PROFIA	2010~2011	4
ADG-CG4ZE	—	2011	1
LKG-CD5ZA	—	2011	3
LDG-CG5ZA	—	2010~2011	19
LKG-CG5ZA	—		
LKG-CG5ZE	—	2011	4
LDG-PW39LT	—	2011	1
LKG-FS54VVY	FUSO	2010	1
LKG-FS54VVZ	FUSO	2010~2011	61
LKG-FS55VVZ	FUSO	2010~2011	10
LKG-FU54VTZ	FUSO	2010~2011	17
LKG-FU54VUZ	FUSO		
		TOTAL	663