

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2950	DATE	June 08, 2012
MANUFACTURE	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>There are cases of fabrication defects with the transmission shift solenoid valve push pin guide holes.</p> <p>As a result, when operating transmission in cold weather before completing idling warm up cycle, there are cases where the solenoid fails to return when shifting the transmission lever into reverse directly after shifting to drive and may result in vehicle traveling forward instead of backward.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-T003	TADANO, GR-250N-2	2008-2012	493
JDS-T006	TADANO, GR-160N-2	2009-2012	110
JDS-EW06	KOBELCO, RK160-6	2008-2012	37
TOTAL			640