

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	2952	DATA	Jun. 14 .2012
MANUFACTURER	Nichijo Manufacturing Co.,Ltd.		
DESCRIPTION OF DEFECT	Filter has been installed in the hydraulic circuit for control-work of the rotary plow. The lack of strength of the cover mounting bolts. When If you continue to operate out of the box, the bolt is broken. It is impossible to operate the steering of the vehicle by the hydraulic oil is leaking. In the the worst case, the hydraulic oil is scattered. There is a risk of fire leading to touch the high temperature of the exhaust system.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-R03C	HTR265	2006~2011	165
JDS-R03C	HTR305	2006~2011	77
JDS-R06C	HTR406	2006~2011	42
R16B	HTR300M	2007~2008	5
JDS-R16C	HTR300M	2009~2011	5
		TOTAL	294